

Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: March 11, 2016 Laboratory Number: 160595

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: David Hart

Enclosed are the analysis results for samples received March 8, 2016 with the Chain of Custody document. The sample was received in good condition, at 7° C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

160595-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.



CERTIFICATE OF ANALYSIS

Client: DCOR, LLC (PF Hillhouse)

Date Sampled: 03/07/16

CAS LAB NO: 160595

Date Received: 03/08/16 Date Analyzed: 03/09/16

Analyst: AV

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
160595-01	Produced Water	5 , 4	1	1.0	5.0

QUALITY CONTROL REPORT

160595-MB Method Blank ND 1 1.0 5.0

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

CO ANALYTICAL					П
S	REPORT:		BILL TO:	0	
tman Avenue	Fax	(805) 535-2075	P.O. #		
CA 93003	Company	DCOR,LLC.	Company:	DCOR,LLC.	
1-1095 Fax 644-9947	Address	290 Maple Court. Suite 290 Address	Address		
F CUSTODY RECORD		Ventura CA. 93003			
	Phone: 805 535-2078 Contact: Jay Rao	Contact: Jay Rao			

CAPCO ANALYTICAL	_					160505
nue .	REPORT:	(805) 535-2075	P.O. #		DCOB I I C	
(805) 644-1095 Fax 644-9947	Address	290 Maple Court. Suite 290		SSS		
CHAIN OF COSTOR LIECCHE	Phone: 805 535-2078	Contact: Jay Rao				
PROJ. NO. PROJECT NAME:	NAME:					
-	ouse			e		-
Produced Water- Weekly	ater- Weekly	CONTAINER TYPES	L sis	eas		3/11
SAMPLER'S SIGNATURE: Donied Hat	*	A=Amber Bottle, G=Glass, P=Plastic, V=Vial, O=Other	ຶ້ nalys	& Gre		-//-
Print Name: DAVID HART		Matrix	Αι)il 8		
Sample Date Time Comp Grab	Sample Description	Vater Soil Sludge Other Container	ner Type	(Remarks
-	Produced Water	_	Α	×		
						Lurbidity: 4, 8 NIU
			1			
						CHECK ONE BOX
						Dispose samples Return samples
Relinquished by (Signature) Date 9 16 3 -8 16	Received by :(Signatus)		elinquished	Relinquished by :(Signature)	2-8-1/	Received by :(Signature)
Print Name: Time 1/EN HINDMAN 0645	Brunden Br	Buchanan	Print Name: Brandes	a Bulanan	Time O'Sec	Print Name:
,	Received by :(Signatu		lelinquishe	y :(8	Date	Received by :(Signature)
Print Name: Liny dig Land 1202	Print Name:	MEY SELIN	Print Name:		Time	Print Name:
Verified by Lead Operator:(Signature)					Turn Around time	time
Print Name:	Time		24Hr.		5 day	
		21.6	48Hr 72Hr		Standard other	×

Tre &

Environmental and Analytical Services-Since 1994 California State Accredited Laboratory in Accordance with ELAP Certificate # 2332

Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: March 17, 2016 Laboratory Number: 160671

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: Jeff Maser

Enclosed are the analysis results for samples received March 14, 2016 with the Chain of Custody document. The sample was received in good condition, at 12°C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

160671-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.



CERTIFICATE OF ANALYSIS

Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 160671

Analyst: AV

Date Sampled: 03/14/16 Date Received: 03/14/16 Date Analyzed: 03/15/16

5.0

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
160671-01	Produced Water	2.5*J	1	1.0	5.0

QUALITY CONTROL REPORT

ND1 1.0 160671-MB Method Blank

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

Note: MDL<J*<PQL

<u> </u>	\vdash		72Hr					
	Standard		48Hr		SELECTION CONTRACTOR SECTION OF THE SEC	000000000000000000000000000000000000000		12.7.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1
	5 day		24Hr.		O200	etsou	II Pint Name:	J,
Ō	Turn Around time	1			3-14-16	r:(Signature) ーナー	Verified by Lead Operator:(Signature)	Verifiedi
Print Name:	Time	ne:	Print Name:	VE YTSKIN	Print Name:	\20 	Lluid Longton	Print Name:
Received by :(Signature)	Date	Relinquished by :(Signature)	Relinquis		:(Signatur	Date 1-1-15	by :(Signature)	Relinquished
Print Name: Upo napobo	OFOU	brance Buhanan	Print Name:	Buchanan	Print Name: Dando		المعلمطالا	Name:
Heceived by :(Signature)	3-14-16	Relinguished by (Signature)	Relinguis	'	Received by :(Signature)	V-C-00-V-0-C-0-V-0-V	Morter	
Dispose samples Return samples								
CHECK ONE BOX								
								,
Produced Water Jemp: 77		×	1 A	×	e,	×	3-14-14 0030	3
Remarks		(Container # Type	Water Soil Sludge Other	Sample Description	Comp Grab	Date Time Sampled Sampled	Sample (NO. Sa
				Matrix		1566	as suu sac	Print Name:
		naly:	ilass,	A=Amber Bottle, G=C P=Plastic, V=Vial, O=Other			SAMPLER'S SIGNATURE	SAMPLER'S
3/16			L	CONTAINER TYPES	Produced Water- Weekly	oduced Wa	1	*.
		se			USE	Hillhouse	Q.	PROJ. NO.
				Contact: Jay Rao	805 535-2078			
				Ventura CA, 93003	Audices	ORD	CHAIN OF CUSTODY RECORD	CHAIN OF
	DCOR,LLC.	Company:		DCOR,LLC.	Company	7	A 93003	Ventura, CA 93003
160671		BILL TO: P.O. #		(805) 535-2075	REPORT:		SERVICES 1536 Eastman Avenue	SERVICES 1536 Eastr
						À	CAPCO ANALYTICAL	CAPC



Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003

Attn: Jay Rao

Report Date: March 29, 2016 Laboratory Number: 160720

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: Ken Hindman

Enclosed are the analysis results for samples received March 21, 2016 with the Chain of Custody document. The sample was received in good condition, at 7° C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

160720-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.

Environmental and Analytical Services-Since 1994 California State Accredited Laboratory in Accordance with ELAP Certificate # 2332

CERTIFICATE OF ANALYSIS

Client: DCOR, LLC (PF Hillhouse)

CAS LAB NO: 160720

Analyst: AV

Date Sampled: 03/21/16 Date Received: 03/21/16

Date Analyzed: 03/23/16

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
160720-01	Produced Water	9.9	1	1.0	5.0

QUALITY CONTROL REPORT

160720-MB Method Blank

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

Note: MDL<J*<PQL

ND

1. 1.0

5.0

VALYTICAL					2 7 2
	REPORT:		BILL TO:		100/
enue	Fax	(805) 535-2075	P.O.#		
ω	Company	DCOR,LLC.	Company:	DCOR,LLC.	
x 644-9947	Address	290 Maple Court. Suite 290	Address		
DY RECORD		Ventura CA. 93003			

														7	5)≤												
P	Verified by Lead Operator:(Signature)	Ling L Bonapolo	Helinguished by :(Sig	DAVID HART	Buil to	Relinguished by /Si								1 3-21-16	Sample Date NO. Sampled	Print Name: ヒたい	SAWIF LED 3 SIGNAT OFF			PROJ. NO.		CHAIN OF CUSTODY RECORD	(805) 644-1095 Fax 644-9947	Ventura, CA 93003	1536 Eastman Avenue	SERVICES	CAPCO ANALYTICAL
Print Name:	d Operator:(\$	mason	1	l		maturo)								0630		ひ エラロンネン	P	1				TODY RECC	-ax 644-9947	Ō3	venue		ANALYTICA
	Signature)			6:45	-									×	Comp Grab	کملاک	del	luced Wa	Hillhouse	PROJECT NAME:		ЯD	7				<u></u>
Time	Date	Print Name:	Received by (Signature)	Stanta	Man Marie	Doogland by (Cionatura)								Produced Water	Sample Description			Produced Water- Weekly	use	NAME:	Phone: 805 535-2078		Address	Company	Fax	REPORT:	
	Ç	CVO T		Buchanas										×	Water Soil Sludge	W	A=Amber Bottle, G=C P=Plastic, V=Vial, O=Other	CONTAIN			Contact: Jay Rao	Ventura	290 Maple C	DCO	(805)		
24		Pr			7 🔌 2			<u> </u>						_	Other Container	Matrix	Bottle, G=Glass, ial, O=Other				lao	Ventura CA. 93003	290 Maple Court. Suite 290	DCOR,LLC.	(805) 535-2075		
24Hr.		Print Name:	linquished	Print Name:	Management		H							Α	ner Type	Aı	્રું naly	·					Address	Com	P.O.#	BILL	
	1		oy :(s	Buhanan	M. H. M.	(C)								×	С	3 li	& Gr	eas	e :			1	ess	Company:	#	BILL TO:	
5 day	urn Around time	Time	Date	0800	3-21-16																			DCOR,LLC.			
	me	Print Name:	Recei	Print Name		L	Dispo	\dagger	+			<u> </u>	Turb	Prod													<u>s.</u>
		vame:	Receive ਖ਼ਤ y :(Signature)	Lloyd Lowapolo	Heceived by :(Signature)	Return samples	Dispose samples	CHECK ONE BOX					Turbidity: 2,97 NTU	Produced Water Temp: 74	Remarks		2/24	2/21/								00//0	- ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・ ・

Fro De

48Hr 72Hr





Prepared for: DCOR, LLC

290 Maple Court Suite #290

Ventura, CA 93003 Attn: Jay Rao

Report Date: March 31, 2016 Laboratory Number: 160759

Project Name: PF Hillhouse Produced Water-Weekly

Sampled by: Felipe Ramirez

Enclosed are the analysis results for samples received March 28, 2016 with the Chain of Custody document. The sample was received in good condition, at 10°C, and it was identified and assigned the laboratory ID number listed below:

SAMPLE DESCRIPTION

CAS LAB NUMBER ID

Produced Water

160759-01

By my signature below, I certify that the results contained in this laboratory report comply with applicable standards for certification by the California Department of Public Health's Environmental Laboratories Accreditation Program (ELAP), both technically and for completeness, and that, based on my inquiry of the person or persons directly responsible for performing the analyses, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete.

Lance Lewy-Laboratory

Director

If you have any further questions or concerns, please contact me at your convenience. This report consists of 1 page excluding the cover letter and the Chain of Custody.



CERTIFICATE OF ANALYSIS

Client: DCOR, LLC (PF Hillhouse)

Date Sampled: 03/28/16

CAS LAB NO: 160759

Date Received: 03/28/16 Date Analyzed: 03/29/16

Analyst: AV

Sample Matrix: Water

OIL & GREASE ANALYSIS EPA METHOD 1664

CAS LAB #	Sample ID	RESULTS (mg/L)	DF	MDL (mg/L)	PQL (mg/L)
160759-01	Produced Water	1.4J*	1	1.0	5.0

QUALITY CONTROL REPORT

160759-MB Method Blank ND 1 1.0 5.0

mg/L: Milligrams/Liter(ppm)

PQL: Practical Quantitation Limit

MDL: Method Detection Limit ND: Not Detected or <MDL value

Note: MDL<J*<PQL

Phot Name Albertson CHAIN OF CUSTODY RECORD Ventura, CA 93003 1536 Eastman Avenue SERVICES Print Name: SAMPLER'S SIGNATURE: (805) 644-1095 Fax 644-9947 CAPCO ANALYTICAL Print Name: Verified by Lead Operator:(Signature) linquished by (Signature) PROJ. NO. 3-28-16 Sampled Date excet-ならず人 Albertsur Later Time Sampled gg Produced Water- Weekly Date ラ28パレ Barrie . 3-28-16 Comp 10-13-10-13-00 50 Time Date Phone: 805 535-2078 PROJECT NAME: Hillhouse Grab REPORT: Print Name: Received by (Signature) Prin Name: Produced Water 3-28-16 Description Sample Company 0700 SON SON P=Plastic, V=Vial, O=Other Contact: Jay Rao \times _{Water} A=Amber Bottle, G=Glass 290 Maple Court. Suite 290 Ventura CA. 93003 CONTAINER TYPES るなのない U. Soil (805) 535-2075 DCOR,LLC. Container # | Typ Type 48Hr 72Hr 24Hr. Print Name: Address P.O. # Company: BILL TO vished by (Signature) **Analysis** Oil & Grease Floor 0.00 Turn Around time DCOR,LLC Standard 5 day Time Turbidity: Produced Water Temp: Print Name: Print Name: Leonapolo neceived by (Signature) Return samples Dispose samples CHECK ONE BOX Remarks 60759 Z